

Drill... Using a bit whose diameter equals the anchor diameter, drill hole to any depth exceeding

minimum embedment. Clean hole

Wedge Anchor

Drive... Assemble anchor with nut and washer so that top of





Expand anchor by tightening nut 3 to 5 turns, or to the specified torque requirement.